Eastbourne Car Auctions

Brampton House
46Brampton Road
Eastbourne, East Susse
BN22 9BN
T01323 520295
F01323 520330

Vehicle Inspection Report

Date Inspected:

Reg: Reg
VIN: GM16 0NR

NAMA Grading

Grade

Appraised By: Eastbourne Car Auctions

General Details

Make HYUNDAI
Model i20 SE
Mileage 67500

Body Type
Fuel Type
Transmission

Doors
Colour
Year of MFR
Date First Reg

Miscellaneous

V5 Location
MOT Location
MOT Expiry
No. Keys

Tyres & Wheels

OSF Depth
NSF Depth
OSR Depth
NSR Depth

Alloys
Tools
Spare

Interior Condition

Carpets
Upholstery
Seats
Parcel Shelf
Odour

Service History

Service History
Stamps

Extras

Metallic Paint
Air Conditioning
Stereo
Keyless Entry
Phone Kit

Central Locking
Sun Roof
Sat Nav
Towbar
Drv Airbag

Interior
Elec Windows
Cruise
Number of Seats
Reversing Camera

Electric Seats
Heated Seats
Xenons
Parking Sensors
EML

Damage Assessment



A Post os

Chipped

1 To 5

Smart Repair



Bonnet

Chipped

1 To 5

Smart Repair



Bumper Front

Poor Previous Repair

Poor Paint

Refinish

Wing nsf



Screen Front

Chipped

UpTo 10mm

Smart Repair



Wing nsf

Poor Previous Repair

Poor Paint

Refinish



Door nsf

Poor Previous Repair

Poor Paint

Refinish

Door nsr

Dented

Between 10mm+ 30mm

Smart Repair



Door nsr

Poor Previous Repair

Poor Paint

Refinish

Qtr Panel nsr

Dented

2 Or Less UpTo 10mm

Smart Repair



Qtr Panel nsr

Chipped

1 To 5

Smart Repair



Bumper Rear

Poor Previous Repair

Poor Paint

Refinish



Bumper Rear Moulding

Broken

Needs Replaced

Replace

Qtr Panel osr

Dented

2 Or Less UpTo 10mm

Smart Repair

Door osr

Dented

2 Or Less UpTo 10mm

Smart Repair



Door osr

Poor Previous Repair

Poor Paint

Refinish



Door osf

Chipped

1 To 5

Smart Repair